





COOLBREEZE TECHNICAL SERVICE MANUAL

INCLUDES MAXIMA INVERTER MOTOR

JANUARY 2019



Models: D095 / D125 / D160 / D195 / D230 / D255



Model: D500 TWIN FAN

COOLBREEZE TECHNICAL SERVICE MANUAL

	PAGE
Statutory & OH & S Obligations	4
Important Product Information	5
CoolBreeze Service Form	6
Service Procedure -	
Pump	7
MagnaSensor MS Float	7
Solenoid	7
Counter-weight Drain Valve	7
Service Maintenance Kit	7
Water Distribution Manifold	8
Sump	8
Powerflow Fan	8
Fan Collet Set	8
Motor	8
Electrical Control Box	9
MRU - Modular Roof Unit	9
Filter Pads	9
Weatherseal	9
Bolt Set	9
Motor Specifications - TAC Induction Motor	10
Motor Anchor Kit	10
Modular Roof Unit -	
PCB & Diagram	11
Multi Unit Control System (MUCS)	12
Fault Finding Guide -	
TAC Induction Motor (non-inverter motor)	13
Maxima Inverter Motor	
PCB & Diagram	15
Dip Switch Speed Setting Chart	15
Fault Finding Guide -	
Maxima Inverter Motor	16
General Specifications	
TAC Induction Motor models D095 - D500	18
Maxima Inverter models D230 - D255	19
Exploded Diagram	
D095 - D255 models	20
D500 Twin Fan model	21
D500 Twin Fan - Identification Information	22
Motor Identification	22

PLEASE READ THIS INSTRUCTION MANUAL CAREFULLY PRIOR TO COMMENCING SERVICE WORK

LEGAL AND STATUTORY OBLIGATIONS

Installation and servicing of CoolBreeze air conditioners must conform to:

- * Building rules and regulations
- * Electrical code
- * Plumbing code
- * Environmental Protection Authority (EPA) rules and regulations
- * and all applicable standards

SAFETY AND O.H.& S. REQUIREMENTS

The safety requirements for each installation/service will be different. Before commencing with the installation or service work, do a full assessment of all factors which maybe hazardous to the installation team, occupants of the building and people in the immediate vicinity.

Installation and servicing usually involves working at heights, therefore particular attention must be given to the following:

- * Footwear suitable for type of roof (metal or tile)
- * Protective clothing to suit environmental conditions
- Access to roof conforms to safety standards
 Ensure roof has access footings and platforms where the roof pitch is greater than acceptable standards
- * Harness anchorage points and/or safety guard-rails are provided where the roof pitch/ height is greater than acceptable standards

IMPORTANT!

The main electrical supply to the unit must be disconnected before installation work commences. If the main electrical supply cable is damaged in any way, it must be replaced by the electrician



It is the policy of AirGroup Australia to continuously review the reliability and safety functions of CoolBreeze air conditioners.

In view of changes introduced in recent years, your attention is drawn to the recommendations listed below.

CAPACITOR:

Capacitors with Plastic casing to be replaced with "NEW LONG-LIFE" P2 Metal cased capacitors **see page 9**

SAFETY ANCHOR:

Motor Anchor Kit to be fitted to units not previously fitted with anchor system. **see page 10**

FAN BLADE:

Pre-2013 models with a 1000 Watt fan motor will require the fan and collet to be replaced with a Powerflow high performance fan and collet. **see page 8**

COOLBREEZE SERVICE FORM

CUSTOMER	DATE			
ADDRESS		TECHNICIAN		
UNIT IDENTIFICATION / LOCATION				
UNIT MODEL		CONTROLLER T	YPE	
SERIAL NO.				
	ELECTRICAL READI	NG	CONDITION	
SOLENOID				
PUMP				
FAN MOTOR				
FILTER PADS				
CABINET				
DRAIN VALVE				
NEXT SERVICE DUE				
COMMENTS				

SERVICE PROCEDURE CHECK LIST

Confirm unit operation before commencing service
Isolate Main Electrical Supply
Remove Lid, Manifold, Louvres & Filter pads
Disconnect 6 pin motor cable & anchor cable. Remove Motor & Fan assembly
Disconnect water riser pipe and remove pump
Clean sump - use only mild soap 7 water - Do not use harsh cleaners or solvents
Remove Pump strainer basket and clean thoroughly. Ensure shaft spins freely.
Test pump coil resistance - should be 40Ω
Disconnect & remove solenoid. Remove & clean inlet filter
Test solenoid coil resistance - should be 38Ω
Re-install solenoid using Service Kit SP2117 - replace hoses, clips and Blue O ring on Drain valve
Before re-installing fan & motor assembly, check following items:
Replace Powerflow Fan & Collet set - pre-2013 models only
Ensure fan location is correct with 5mm of motor shaft exposed
Check motor body for indications of excesive temperature eg: discolouration etc
Check motor cable - check rubber boot where cable enters motor - check for discolourisation of connector
- replace if damaged or discoloured
Perform Resistance check of motor
Place Motor & Fan assembly back into sump. Reconnect 6 pin plug and anchor cable
Spin motor by hand to ensure it spins freely - listen for bearing noises indicating potential issues
Restore power to unit and using test controller check motor current draw
Check Motor minimum and maximum fan speeds
BLACK

Motor can also be tested by connecting to mains 240VAC power supply. Connect as shown ...



SERVICE PROCEDURE

	DUMD	502380
OLD PUMP SP2127 - NLA	Note: pre-2015 JRM pump (SP2127) replaced by Super Pump (SP2380) - SP2127 no longer available Check pump resistance = 40Ω / operating 240vac Run pump - visual check for vibration / correct operation Listen for abnormal sounds - damaged bearings etc Check hoses and clips for damage	1
	Remove basket and clear debris Super Pump only - clear impeller	
diam.	MAGNASENSOR (MS) - WATER LEVEL CONTROL SYSTEM	SP2212
DECREASE INCREASE LEVEL LEVEL	BALL FLOAT Check Magnasensor operation - controlling pump on/of Check Float level adjust ball float - turn ball clockwise to decrease level - turn ball anti-clockwise to increase lev	SP2200 f
	SOLENOID Check solenoid resistance = 38Ω / operating 24 vac Turn unit to COOL - water entering unit Check solenoid operation - controlling pump on/off Remove inlet filter and clean	SP2031
	COUNTER-WEIGHT DRAIN VALVE Turn unit to COOL - check drain valve closes completey Replace hoses Replace clips Replace Blue O-ring	SP2040 KIT
	SERVICE MAINTENANCE KIT	SP2117
500	contains: 1 x Blue O-ring 2 x Hoses 4 x Hose Clips	

SERVICE PROCEDURE

	WATER DISTRIBUTION MANIFOLD	SP2009
	Check manifold to ensure all holes are clear NOTE: poor water quality can cause scale build-up on holes Check Riser pipe for splits - replace in necessary	
	SUMP Twin Fan	SP1009B
	Remove any debris from sump including under pads etc Wipe out sump - only use mild soap & water DO NOT USE HARSH DETERGENTS OR SOLVENTS ON CABINET	;
	POWERFLOW FAN BLADE	SP6072
	COLLET SET (NEW)	SP6073
	Spin Fan by hand to ensure it is not catching on sump Rock fan to ensure it is not loose on shaft Run fan motor - check fan is running true NOTE: if any fan issues are evident - replace fan with NEW fan & collet set. FAN COLLET SET	SP6073
	Check if collet has moved down shaft	
	Maximum 5mm of shaft visible above collet plate	
	down shaft - COLLET MUST BE REPLACED (+ fan for pre-2013 model	s)
	NOTE: Circlip fits above collet plate	
Cold Data Plate	 MOTOR - 1000W RUN MOTOR AT 100% Visual: Check motor running true & straight / no vibrat Audio: Check for normal blade / air noise Investigate any vibration / unusual noise Check Fan Speed with Tachometer - approx. 1350RPM @ 10 Tong test motor - should be 5.5-6 Amps @ 100% If higher, check bearings or motor windings Test Voltage of terminals - should be xxx @ 100% Check rubber motor mounts - replace if deformed Check if 6 pin plug (also MRU plug) replace if discolouree Check rubber boot where cable enters motor 	SP6015 ion 00% ing

SERVICE PROCEDURE



MOTOR SPECIFICATIONS - TAC INDUCTION MOTOR

MOTOR SP	ECIFICATIONS	600 WATT	750 WATT	1000WATT	
- COLD MC	DTOR	MOTOR	MOTOR	MOTOR	
Motor Winding Resistance ± 1	0%				
Black & White Wire (Star	t Winding)	6.5 Ω	5.5 Ω	4.5 Ω	
Brown & Blue Wire (Run	Winding)	5.0 Ω	4.0 Ω	2.5 Ω	
Fan Blade Revolutiuons Per M	inute (RPM)				
Minimum Fan Speed		750 rpm	750 rpm	850 rpm	
Maximum Fan Speed		1350 крм	и 1350 крм 1350 крм		
Motor Current Draw					
Minimum Fan Speed		2.0 amps	3.3 amps	5.0 amps	
Maximum Fan Speed		4.0 amps	4.1 amps	6.0 amps	
Operating Voltage					
Minimum Fan Speed: Orange & White Wire		100 v	100 v 100 v		
	Orange & Brown Wire	110 v	110 v	110 v	
Maximum Fan Speed:	Orange & White Wire	300 vac	300 vac	300 vac	
	Orange & Brown Wire	240 vac	240 vac	240 vac	

MOTOR ANCHOR KIT - RECOMMEND FITTING TO ALL UNITS						
	MOTOR ANCHOR KIT SECURING MOTOR ANCHOR CABLE TO SUMP (IF NOT ALREADY FITTED) STEP 1 The Motor Anchor Cable is fitted to the base of the motor	SP6048				
	STEP 2 Attach anchor cable to motor extension cable with cable ties Push the anchore cable and motor extension cable through the hole in the sump casing					
	STEP 3 Secure the anchor cable to the sump using a Tek screw and the large washer supplied.					





MULTI UNIT CONTROL SYSTEM [MUCS] - operate up to 99 units from 1 keypad

Order one less MUCS Board than total number of units operating from one keypad. eg: 4 units operating from one keypad - order 3 x MUCS Boards

٢





FAULT FINDING - TAC INDUCTION MOTOR (not inverter motor)

ELECTRICAL FAULTS					
FAULT	Ref	CAUSE	ACTION		
1. NO DISPLAY AT KEYPAD	1.1	Display illumination level set too low.	Whilst in 'OFF' mode adjust illumination with speed > (increase) button.		
	1.2	240v mains supply isolated.	Check mains fuse, circuit breaker, unit isolation switch or MRU.		
	1.3	Keypad not connected.	Check 7-pin cable connection and continuity.		
	1.4	Keypad locked up.	Push 'RESET' button on keypad. (refer to Owners Manual)		
	1.5	MRU failure.	Check voltage between pins 1 and 7 - if not 17vdc replace MRU		
	1.6	Keypad failure.	Verify control signal from keypad with indicator LED's on MRU. Check using substitute keypad.		
2. NO RESPONSE	2.1	Keypad failure.	Check appropriate LED on MRU.		
FROM KEYPAD	2.2	MagnaSensor (MS) board failure.	Remove 3 pin MS cable from MRU & check unit operation. : Pump & Solenoid should operate together.		
	2.3	No output to selected components.	Replace MRU.		
		FAN F	AULTS		
FAULT	Ref	CAUSE	ACTION		
3. FAN NOT	3.1	Keypad failure, no signal to MRU.	If speed LED not lit on MRU suspect keypad cable.		
OPERATING	3.2	MS board failure. Refer 2.2	Remove 3-pin MS cable and confirm motor operation.		
Select 'FAN' at keypad and fault find as follows	3.3	Capacitor failure (motor will buzz but not rotate).	Replace capacitor.		
	3.4	Motor not powered.	Check motor power cable is connected properly - check connections at both ends of the cable - motor & MRU		
	3.5	Motor seized.	Replace motor.		
	3.6	Fan jammed in cowling.	Centralise fan in cowling.		
	3.7	MRU failure.	Verify output with voltmeter between orange & brown, and orange & white motor terminals.		
	3.8	Motor failure or shutdown due to internal (motor) thermal protection (thermal overload).	Check run current, if running at more than 120% of value on motor name plate – replace motor.		
4. FAN WILL NOT	4.1	Any of the above FAN faults.	Check 3.1 to 3.7 above.		
OPERATE IN EXHAUST	4.2	Keypad has no signal to roof unit.	If exhaust & speed LED's are not lit on MRU check for faulty keypad cable or controller.		
Select 'EXHAUST' at keypad and fault find as follows	4.3	MRU failed or locked up.	If exhaust & speed LED's are lit yet motor direction has not reversed replace MRU.		
5. FAN CONSTANTLY RUNNING	5.1	MRU triac shorted.	If fan runs with keypad 'OFF' or unplugged replace MRU.		
6. FAN TURNS ON BY ITSELF (AND	6.1	Unit has sustained an electrical spike on supply cable.	Confirm unit is wired on its own dedicated supply.		
CANNOT BE TURNED OFF AT KEYPAD)	6.2	Unit has sustained an electrical spike on the low voltage keypad cable.	Fit a spike filter (SP3242) on both ends of the low voltage keypad cable.		
7. FAN CUTS OFF	7.1	Loss of power to air conditioner.	Check display on keypad, if keypad illuminated - suspect thermal overload.		
	7.2	Loss of power to motor.	Confirm keypad is in 'ON' position.		
	7.3	Motor failure due to internal (motor) thermal overload protection	Check run current, if running at more than 120% of value on motor name plate – replace motor.		

FAULT FINDING - TAC INDUCTION MOTOR (not inverter motor)

		WATER	RFAULTS
FAULT	Ref	CAUSE	ACTION
8. WATER NOT	8.1	Isolation tap closed or filter blocked.	Open tap and/or clean filter.
ENTERING UNIT	8.2	Solenoid time delay active.	Wait 1 min for drain valve to close & delay to end.
Select 'COOL' at key-	8.3	Keypad not signalling roof unit.	Confirm drain is lit, if not suspect faulty keypad or control cable.
follows	8.4	No 24vac output Water Inlet on MRU.	Replace MRU.
	8.5	MS board failure.	Remove 3-pin MS cable,
		4.4.4	Test solenoid coil resistance - should be 38Ω
	8.6	Solenoid mesh strainer blocked.	Remove solenoid, clean mesh strainer & check water quality. Recommend replace solenoid.
	8.7	Solenoid coil open circuit or failed.	Replace solenoid.
	8.8	Pressure lock between solenoid & non- return type isolation valve.	Relieve pressure & fit standard isolation tap.
9. WATER	9.1	Keypad failure.	If drain LED not lit suspect 7-pin cable or keypad.
CONTINUALLY	9.2	MS board failure. refer 2.2	Remove 3-pin MS cable from MRU.
RUNNING FROM UNIT	9.3	Solenoid passing water continuously.	Strip & clean solenoid diaphragm and seating. Recommend replace solenoid.
Select 'COOL' at key-	9.4	Water level set too high.	Adjust MS float. Check for water in float.
paa ana jaut jina as follows	9.5	Counterweight Drain Valve:	Replace plastic clips (SP2041) or hoses kit (SP2042).
		a) Leaking from hoses or plastic clips.	Do not re-use clips.
		b) Hoses incorrectly connected.	Replace hoses kit (SP2042).
		 c) Physical or mechanical damage to counter-weight drain valve body. 	Replace drain valve (SP2040).
	9.6	Square section blue 'O' ring faulty.	Replace 'O' ring (SP2043).
10. WATER NOT	10.1	Unit may be in AUTO mode.	Check system mode at keypad.
DRAINING FROM	10.2	Counterweight Drain Valve:	Replace drain valve (SP2040).
		a) Stuck in closed position.	
		b) Blockage in components.	Replace drain valve (SP2040).
	11.1	Reypad failure – display reading "C".	If pump LED on MRU not lit suspect keypad cable.
Select 'COOL' at key- pad and fault find as	11.2	operation.	wait 1 min after solehold operation for pump to start.
follows	11.3	Roof unit failure – no 240v supply to pump.	If pump LED on MRU lit and 240v not present at terminals replace MRU.
	11.4	MS failure.	Remove 3 pin MS cable from MRU & check unit operation. : Pump & Solenoid should operate together. : Replace MS MagnaSensor Unit
	11.5	Pump seized, impeller stripped or base cracked.	Replace pump.
	11.6	Pump strainer basket clogged.	Remove & clean strainer basket.
	11.7	Water distribution manifold blocked.	Remove and flush manifold of any blockages.

MAXIMA INVERTER MOTOR





DIP SWITCH SPEED SETTING CHART										
MODEL	FAN	DIP S	WITC	Н						
MD095	Grey / Green	0H FLED ADE08	OFF 1	OFF 2	ON 3	OFF 4	ON 5	ON 6	0N 7	OFF 8
MD125/C125	Grey / Green	ON FILCO ADE080	OFF 1	OFF 2	OFF 3	OFF 4	OFF 5	OFF 6	OFF 7	ON 8
MD160/C160	Grey / Grey	0N RLCD ADE08	OFF 1	OFF 2	ON 3	OFF 4	OFF 5	OFF 6	0N 7	ON 8
MD195/C205	Black Powerflow	ON RLED ADE08	OFF 1	OFF 2	ON 3	ON 4	OFF 5	OFF 6	OFF 7	ON 8
MD230/C240	Black Powerflow	0N RLED ADE 088	OFF 1	OFF 2	OFF 3	ON 4	OFF 5	ON 6	OFF 7	ON 8
MD255	Black Powerflow	0N RLED ADE08	OFF 1	OFF 2	ON 3	OFF 4	OFF 5	OFF 6	0N 7	ON 8

FAULT FINDING - MAXIMA INVERTER MOTOR

ELECTRICAL FAULTS				
FAULT	Ref	CAUSE	ACTION	
1. NO DISPLAY AT KEYPAD	1.1	Display illumination level set too low.	Whilst in 'OFF' mode adjust illumination with speed > (increase) button.	
	1.2	240v mains supply isolated.	Check mains fuse, circuit breaker, unit isolation switch and red LED on ECRU.	
	1.3	Keypad not connected.	Check 7-pin cable connection and continuity.	
	1.4	ECRU failure.	If 17 vdc not present between pins 1 and 7 replace ECRU.	
	1.5	ECRU failure.	Verify control signal from keypad with indicator LED's on ECRU.	
			Check using substitute keypad.	
2. NO RESPONSE FROM KEYPAD	2.1	Keypad failure.	Select desired function and confirm the appropriate LED is illuminated. If no LED's suspect faulty keypad or control cable	
3. KEYPAD SHOWS UNIT IS OPERATING BUT THERE IS NO AIRFLOW	3.2	The Current Limit protection on the motor has been activated	Check to see if there is any obvious causes. Reset the unit by turning off the mains supply then re-start unit. If the motor stops again within 10 seconds - Thermal overload switch has activated - replace motor	
FAULT	₽ Ref	TTENTION: Be advised that the Maxima I before starting and incorporates a r CAUSE	Inverter Motor has a delay time period ramp up / ramp down operation ACTION	
3. FAN NOT	3.1	Keypad failure, no signal to ECRU.	If fan LED not lit on ECRU check for faulty keypad cable.	
OPERATING	3.2	Motor not powered	Check multipin jack plug between the motor and the ECRU.	
Select 'FAN' at	3.3	Motor not powered	With the unit in standby function, confirm 240vac present at motor power cable. If no voltage present replace ECRU.	
keypad and fault	3.4	Motor seized.	Replace motor.	
find as follows	3.5	Fan jammed in cowling.	Centralise fan in cowling.	
	3.6	ECRU failure. H ₂ MOTOR 1234	Confirm 5 vdc between terminal 1 & 2 . Select "FAN" confirm 1.2/2.6vdc present between ter- minals 2 & 3 depending on fan speed selected. If no voltage present replace ECRU.	
4. FAN WILL NOT	4.1	Any of the above FAN faults.	Check 3.1 to 3.6 above.	
OPERATE IN EX- HAUST	4.2	Keypad has no signal to roof unit.	If EXH & FAN LED's are not lit on ECRU check for faulty keypad cable or controller.	
	4.3	ECRU failure H ₂ MOTOR	If EXH & FAN LED's are lit confirm voltage between ter- minals 1 & 2 is 5vdc, voltage between terminals 2 & 3 is 1.1/1.7vdc depending on fan speed selected, and the voltage between terminals 2 & 4 is 5vdc. If these volt- ages are present replace the motor, if these voltages are not present replace the ECRU.	
5. FAN CUTS OFF	5.1	Loss of power to air conditioner.	Check display on keypad, if keypad illuminated check for possible thermal overload. Refer to 3.2	

FAULT FINDING - MAXIMA INVERTER MOTOR

WATER FAULTS								
ATTENTION: Be advised that the MS control unit does NOT switch power to the								
	pump and solenoid when removed from the ECRU.							
FAULT	Ref	CAUSE	ACTION					
6. WATER NOT ENTERING UNIT	6.1	Isolation tap closed or filter blocked	Open tap and/or clean filter.					
Select 'COOL' at key- pad and fault	6.2	Keypad is not signalling ECRU.	Confirm RX and H2O LED is illuminated, if not check for faulty keypad or control cable.					
find as follows:	6.3	MS failure	With keypad OFF Voltage between terminal 1 & 3 should be 5vdc With keypad ON Voltage between terminals 2 & 3 should be 5vdc If these voltages are not present replace ECRU.					
	6.4	No 24vac output to solenoid	Replace MS to confirm either MS or ECRU fault					
	6.6	Solenoid mesh strainer blocked.	Remove solenoid, clean mesh strainer & check water quality. Recommend replace solenoid.					
	6.7	Solenoid coil open circuit or failed.	Coil resistance should be 38Ω					
	6.8	Pressure lock between solenoid & non- return type isolation valve.	Relieve pressure & fit standard isolation tap.					
7. WATER CONTINUALLY	7.1	Keypad failure. If RX and /or H2O LED are not lit check for faulty 7-p keypad.						
RUNNING FROM	7.2	MS board failure. refer 2.2	Remove 3-pin MS cable from ECRU.					
UNIT	7.3	Solenoid passing water continuously.	Strip & clean solenoid diaphragm and seating. Recommend replace solenoid.					
	7.4	Water level set too high.	Adjust MS float. Check for water in float.					
Select 'COOL' at key- pad and fault	7.5	Counterweight Drain Valve a) Leaking from hoses or plastic clips.	Replace O ring, hoses & clips from Service Kit (SP2117) Do not re-use clips.					
find as follows		b) Hoses incorrectly connected.	Replace O ring, hoses & clips from Service Kit (SP2117) Do not re-use clips.					
		c) Damage to body of Counter-weight drain valve counterweight drain valve body.	Replace drain valve (SP2040).					
	7.6	Square section blue 'O' ring faulty.	Replace O ring, hoses & clips from Service Kit (SP2117) Do not re-use clips.					
8. WATER NOT	8.1	Unit may be in AUTO mode.	Check system mode at keypad.					
DRAINING FROM	8.2	Counterweight Drain Valve	Replace drain valve (SP2040).					
UNIT		a) Stuck in closed position.						
		b) Blockage in components.	Replace drain valve (SP2040).					
9. WATER NOT	9.1	Keypad failure.	If RX and/or H2O LED are not lit check for faulty 7 pin cable or					
CIRCULATING	9.2	ECRU failure	keypad - Refer 6.3/6.4					
Select 'COOL' at key- pad and fault	9.3	Pump seized, impellor stripped or base cracked.	Replace pump.					
find as follows	9.4	Pump strainer basket clogged.	Remove & clean strainer basket.					

GENERAL SPECIFICATIONS - TAC INDUCTION MOTOR

MODEL		D095	D125	D160	D195	D230	D255	D500	
Motor	Voltage (50 Hz)	220-240 SINGLE PHASE							
	Thermal Protection: 1x Auto Reset and 1x Manual Reset	Yes							
	Insulation	"B" Class	"B" Class	"F" Class					
	Capacitor – uf	25	25	30	30	30	30	30	
	Resistance - Windings	5.01/	5.01/	4.03 /	2.34 /	2.34 /	2.34 /	2.34 /	
	Main/Aux at 20°C	6.65	6.65	5.36	4.43	4.43	4.43	4.43	
	Watts Model TACEVA VS	600	600	750	1000	1000	1000	2x1000	
	Amp Draw - low/high	2.65/3.6	2.65/3.6	2.7/5.6	2.9/6.0	2.9/6.0	2.9/6.0	2.9/6.00	
	RPM - Low	600-750	600-750	600-750	850	850	850	850	
	High	1300	1300	1300	1370	1370	1370	1370	
Fan	Auswing II 35° Pitch	х	Х						
	Auswing II 40° Pitch			Х					
	PowerFlow Fixed Pitch				Х	Х	Х	Х	
	Diameter (mm) - fitted in shrouded motor ring	528	528	528	528	528	528	524	
Pump	Voltage (50 Hz)`	220-240							
	Thermal Overload - UL cert.	Yes							
	Insulation	'C' Class							
	Performance - litres per	20 E							
	minute at 600mm	23.5							
	Current – Amps	0.44A							
Water	Inlet Connection	½ inch BSP							
	Drain (DVW)	40mm							
	Drain Optional		19mm Barb						
	Tank Capacity (litres)	10 - 12 18 - 20							
	Drain Valve	Yes							
	Provision for Bleed-off	Yes							
	Water Level	Hall Effect Sensor							
Filter Media	Number of Filter Pads				4			6	
	Size - Width (mm)	830	830	830	830	830	830	2 x 928	
	Size - Height (mm)	370	460	460	535	650	//0	2 x 960	
	Size - Width (mm)							2 x 960	
Air Flow (Lit/see @ 60 De	Size - Height (mm)	1050	2120	2250	2910	2010	2000	2 X 645	
All Flow (Lit/set @ 60 Pa)		64/52	64/52	2350	2810	66/53	66/53	83/63	
Denth/Width (mm)		04/32	04/32	1130	x 1130	00/33	00/33	1630 x 1200	
Height (mm)		540	630	630	705	820	940	1160	
Height Above Dropper (mm)		310	400	400	475	590	710	910	
Dropper Size (mm)		550 x 550 1165 x 585							
Shipping Weight (kg)		44.5	46	48	54	56.5	58.5	101	
Ship Vol m3 (within Australia)		0.645	0.72	0.73	0.8	0.81	0.865	1.6	
Operating Weight (kg)		55	57.5	60	66.5	69	71.5	114	

GENERAL SPECIFICATIONS - MAXIMA INVERTER MOTOR

MODEL		D230 D255					
Motor	Frequency	50 / 60 Hz					
	Current Limit Protection	Yes					
	Insulation	"B" Class					
	Power Supply	AC 220v - 240v SINGLE PHASE					
	Watts Model HFM017	930 1060					
	Amp Draw @240V - low/high	0.2 / 3.7 0.2 / 4.3					
	RPM - Low	400 400					
	High	1230 1330					
	Performance Setting	43 50					
Fan	Auswing II 35° Pitch						
	Auswing II 40° Pitch						
	PowerFlow Fixed Pitch	X X					
	Diameter (mm) - fitted in	526 526					
	shrouded motor ring	520 520					
Pump	Voltage (50 Hz)`	220-240v					
	Thermal Overload - UL cert.	Yes					
	Insulation	'C' Class					
	Performance - litres per	29.5					
	minute at 600mm	25.5					
	Power @ 1m head	0.44A					
	Amps/Watts						
	RPM @ 1m head	2550					
Water	Inlet Connection	½ inch BSP					
	Drain (DVW)	40mm					
	Drain Optional	19mm Barb					
	Tank Capacity (litres)	10 - 12					
	Drain Valve	Yes					
	Water Level	Hall Effect Sensor					
Filter Media	Number of Filter Pads	4 4					
	Size - Width (mm)	830 830					
	Size - Height (mm)	650 770					
	Thickness (mm)	100 100					
Air Flow (Lit/sec @ 60 Pa)		5510 5650					
dB - Measured at 1m - High/Low		65/53 65/53					
Depth/Width (mm)		1130 x 1130					
Height (mm)		850 970					
Height Above Dropper (mm)		590 710					
Dropper Size (mm)		550 x 550					
Shipping Weight (kg)		57.5 59.5					
Ship Vol m3 (within Australia)		0.81 0.865					
Operating Weight (kg)		70 72.5					

EXPLODED VIEW - D series 095 - 255





When fault finding on the D500 Twin Fan model, first identify the Primary and Secondary Modular Roof Unit (MRU).

Open each Electrical Control Box:



The Primary MRU Box has an additional circuit board inside > The Primary MRU is on the side of the unit with the Counter-weight Drain Valve fitted.



MOTOR INDENTIFICATION

TAC INDUCTION MOTOR SILVER LABEL



TAC INDUCTION MOTOR GOLD LABEL MANUAL RESET THERMISTOR



MAXIMA INVERTER MOTOR





•

Head Office & Manufacturing AirGroup Australia 28 Division Street Welshpool WA 6106 Phone: 08 9350 2200 Fax : 08 9451 3077

Email: service@airgroup.com.au

AUSTRALIA FM392/0119